

Internal Service Bulletin for JLG Use Only ISB 10-20

<u>Release Date:</u>	July XX, 2010
<u>Subject:</u>	Elevation Switch Cover
<u>Product Type:</u>	Scissors
<u>Models Affected:</u>	ES Scissors
<u>Switch</u>	Rotary Angle Sensor
<u>Part Numbers Involved:</u>	1001092354 (Switch Assembly), 1001121241 (Service Kit)

Problem Statement:

A change was made to the cover supplied on elevation rotary angle sensor (1001092354). The cutout width was increased to allow clearance for the wires to eliminate the rubbing condition which could result in the sensor not operating properly. Photos below show the affected part.



Original cover shows wires exiting off center of the cover causing the rubbing condition.



Modified cover shows wires centered exiting cover eliminating the rubbing condition.

Resolution:

A service kit# 1001121241 has been created. This kit contains an updated cover (3200454) and the rotary angle sensor which needs to be used in place of the original. Any time a customer orders the original switch number he will receive the service kit in it's place. The customer should discard the original cover and replace it with the new cover.

Warranty :

Standard warranty applies for machines in the warranty period.

Contacts: Should you have any questions or request additional information with the above Service Letter, please contact:

JLG Customer Support
North America @ 1-877-554-5438.
Europe @ +44 (0) 141 781 6725.

Internal Use Only