



The Source for Power...
Worldwide™

Technical Bulletin

To: FPP Distributors Distributor OEMS

TB-217-01

FPP Personnel Marine OEMS

Date: May 14, 2001

Direct OEMS Service Dealers

Product: VSG 411/413

Classification: Service parts

Sub-Classification: Ignition system

Subject: Service Kit – ICM Jumper Harness

A new service kit has been developed for the VSG 411/413. The kit should be used when replacing an old ICM (89FB-12A297-GA) with a new ICM (YU1L-12A297-FA). This will allow a new ICM to be used on a wire harness set up for the old ICM.

Service kit 1U1L-12K062-AA

- YU1L-12A297-FA ICM -
- F8JL-9S428-AB Map Sensor -
- YU1L-14N118-AA Wire Harness Jumper

If you have any questions, please contact Seth Holdeman at 248-945-4414.

Seth Holdeman
Applications Engineer