





**Stacy L
Simmons/AMERICAS/JLG**
10/10/2007 06:42 AM

To A. Ray Watkins/MCB/JLG@JLG
cc Gary E Clark/AMERICAS/JLG@JLG
bcc
Subject Re: 3841517s 

History:  This message has been replied to and forwarded.

Ray,

These all are packaged in a bag with the sticker of that saying. Here is a copy. Let me know if you need anything else.




DOC101007.pdf

Thanks :)

Have a Blessed Day!

Stacy Simmons
Distribution Specialist
JLG Industries, Inc.
600 E. Chestnut St.
Orrville, OH 44667
Phone: 330-684-0142
Fax: 330-6840197
slsimmons@jlg.com
A. Ray Watkins/MCB/JLG



A. Ray Watkins/MCB/JLG
10/09/2007 03:32 PM

To Stacy L Simmons/AMERICAS/JLG@JLG
cc Gary E Clark/AMERICAS/JLG@JLG
Subject 3841517s

Stacy,

Would you please check the service inventory on P/N: 3841517S
The vendor is suppose to supply that tie-rod end with a document that states to set steer pressure to 1400PSI.

I'm looking for:

- (1) Is the vendor supplying that document
- (2) If so, I need to see a copy of that document.

Thanks in advance,

A. Ray Watkins
Mgr, Technical Service - AWP
JLG Industries, Inc.
1 JLG drive

**"STEER RELIEF PRESSURE MUST
BE RESET TO 1400 PSI IF USED
ON JLG MODEL E/M400AJPN,
OK AS IS ON ALL OTHER MODELS"**