

P/N 520054 Steering Power Pack supersedes P/N 520102 & 520103. When replacing 520102 or 520103 by 520054 the power pack should be mounted 180 degrees to the original.

520054 Electric Motor to the Rear

