

Item 70030553 must read information.

Comments: Part number 70030553 - Reservoir

Units built with Cummins DEF solution and failed under the Emission warranty coverage of 5 yrs. and 3,000 hrs., need to contact Cummins at 1-800-CUMMINS for service support

If the unit is outside the Emission warranty coverage or repair is not warrantable, JLG does offer aftermarket service parts

JLG does not provide Emission warranty coverage on units converted to or built with the Cummins Diesel Exhaust Fluid system.