

JLG p/n 7029314 is no longer available and does not have a direct replacement. For proper service replacement please choose from the following options:

If replacing p/n 7029314 on front axle p/n 91563067 you must purchase universal joint shaft assembly p/n 70024208 (qty. 2)

If replacing p/n 7029314 on front axle p/n 91563282 before DANA axle s/n RITA711344 you must purchase universal joint shaft assembly p/n 700024208 (qty. 2)

If replacing p/n 7029314 on rear axle p/n 91563283 before DANA axle s/n KITA737006 you must purchase all of the following parts to make interchangeable:

- p/n 70021611 - Oring (qty. 2)
- p/n 70021610 - Oring (qty. 2)
- p/n 70021604 - Bolt (qty. 40)
- p/n 91514165 - Tube(Spring) (qty. 6)
- p/n 7029785 - Adjusting Bolt (qty. 6)
- p/n 70021608 - Piston (qty. 2)
- p/n 70021606 - Spacer (qty. 2)
- p/n 70021609 - Backup Ring (qty. 2)
- p/n 91514160 - Adjusting Bolt (qty. 6)
- p/n 70021613 - Pilot Bolt (qty. 2)
- p/n 91514159 - Spring (qty.6)
- p/n 70021612 - Backup Ring (qty. 2)
- p/n 70022141 - Intermediate Cover (qty. 2)
- p/n 70022142 - Locking Plate (qty. 2)
- p/n 70021943 - Axle Case (qty. 2)
- p/n 70021602 - Double Universal Joint (qty. 2)

Please note both sides of the axle must be updated at the same time. Once all required updates have been made service parts can then be ordered on an as needed basis.